



PO Box 455 • Lombard, IL 60148
630-991-7807
rich@kemecraneservices.com

Fax# 630-932-9157

Beacon Funding
3400 Dundee Rd
Northbrook, IL 60062

Work Order # CI-51410-BF796

PO # _____

ANNUAL CRANE INSPECTION

Deficiencies are listed separately

Date: 5/14/2010 Location: Elgin Unit #:
Make: Phoenix Model: Skyhoist Serial #: SX57 626796
Max Capacity: 300 lbs bskt, 6000 lbs hoist Boom Length: 57' Hours: unk

Crane Description: truck mounted, boom/platform lift

Services performed: Annual Crane Inspection

Notes:

Hours _____ x \$ _____ Miles _____ x \$ _____ **Total \$ 300**

This is a visual inspection only. It determines if this unit is in compliance with OSHA standards #1926.550 / 1910.180 at time of inspection only .

Signatures:

Company Rep _____ Inspector: Richard Walsh

